

Oil Field Environmental Incident Summary

Incident: 20150426233800 **Date/Time of Notice:** 04/26/2015 23:38
Responsible Party: QEP ENERGY COMPANY
Well Operator: QEP ENERGY COMPANY
Well Name: MHA 8-06-01H-149-92
Field Name: HEART BUTTE **Well File #:** 29714
Date Incident: 4/24/2015 **Time Incident:** 18:00 **Facility ID Number:**
County: DUNN **Twp:** 149 **Rng:** 91 **Sec:** 5 **Qtr:** NE NW
Location Description: Independence Point off of BIA 13

Submitted By: Jerry Reinisch **Received By:**
Contact Person: Jerry Reinisch
1050 17TH ST STE 500
DENVER, CO 80265

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 3.8 Mile
Distance Nearest Water Well: 3.8 Mile

Type of Incident: Other

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	4000		4000		4000	

Description of Other Released Contaminant:

4000 pounds of Solibond Cement dust (CKDI) used in the solidification processing of drill cuttings

Inspected: **Written Report Received:** 3/1/2016 **Clean Up Concluded:** 4/25/2015

Risk Evaluation:

Low environmental risk

Areal Extent:

Approximately a two mile stretch of BIA 13 (Independence Point Road)

Potential Environmental Impacts:

Any residual material will probably strengthen the graveled road surface

Action Taken or Planned:

The material was bladed into a wind row and loaded into a side dump for transport to a disposal facility. The area impacted was cleaned up with QEP supervision.

The Solibond bulk silo will no longer be stationed along with QEP rig Unit 329.

Wastes Disposal Location: The recovered material was transported to a Nuverra Environmental Solutions disposal site by Nuverra.

Agencies Involved: BIA Environmental, MHA Energy, MHA Environmental

Updates

Date: 4/27/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this incident occurred within the MHA Nation boundaries. Forward to BIA/Tribal authorities.